

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/16/2018

Submitted Date:

06/08/2018

Document Number:

688800146

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
335876 _____ Hughes, Jim _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10091
Name of Operator: BERRY PETROLEUM COMPANY LLC
Address: 5201 TRUXTUN AVENUE #100
City: BAKERSFIELD State: CA Zip: 90339

Findings:

- 8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Johnson, Derek	970-285-2200	djohnson@bry.com	Dist. Superintendent
Armstrong, Jon		jarmstrong@bry.com	
Wilbourn, Don		dwilbourn@bry.com	
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
335876	LOCATION	AC			-	GRANLEE OM C10 696	EI
449190	LAND APPLICATION SITE	AC	02/10/2017		-	C10 696 449190	EI
450300	PIT	AC			-	C10 696 335876	EI

General Comment:

On May 16, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Berry Petroleum OM C10 696 Land Application Site, Facility ID #449190. COGCC West Environmental Supervisor Alex Fischer and Berry Petroleum representatives Derek Johnson and Don Wilbourn were present during this inspection. For the most recent field inspection report for this facility, please refer to document #689700329. The purpose of this environmental field inspection was to document the status of REM #10240.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign near location entrance.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Posted on location sign.		
Corrective Action:		Date:	

Good Housekeeping:			
Type	DEBRIS		
Comment:	Continue to remove liner pieces as they become exposed in land farmed material.		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 335876 Type: LOCATION API Number: - Status: AC Insp. Status: EI

Facility ID: 449190 Type: LAND API Number: - Status: AC Insp. Status: EI

Facility ID: 450300 Type: PIT API Number: - Status: AC Insp. Status: EI

Environmental

Spill/Remediation:

Comment: [Please refer to REM #10240 in the COGIS database for more information regarding this project.](#)

Corrective Action:

Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	

Comment: Perimeter berm around land farmed material.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Drilling Pit Lined: _____ Pit ID: 450300 Lat: 39.543698 Long: -108.095506

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: g

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: _____ 2+ feet Freeboard: _____

Comment:

Corrective Action

Date: _____

COGCC Comments

Comment	User	Date
On May 16, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Berry Petroleum OM C10 696 Land Application Site, Facility ID #449190. COGCC West Environmental Supervisor Alex Fischer and Berry Petroleum representatives Derek Johnson and Don Wilbourn were present during this inspection. For the most recent field inspection report for this facility, please refer to document #689700329. The purpose of this environmental field inspection was to document the status of REM #10240. Rocks >6" have been partially screened from the land farmed material with a track hoe to allow remaining material to be spread out thinner. Rocky debris has been stockpiled on site. Land farmed material is up to 6' thick on this location.	hughesj	06/08/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800147	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4489554