

Final Reclamation Inspection

June 11, 2018

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC - #8960

API: 05-123-24326

Inspection Document #: 682403686

Weld County, CO

NWNW Section 12 T5N R62W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: STATE ANTELOPE #11-12
API: 05-123-24326



Photo 1. Photo taken from the entrance of the location, facing West. Photo illustrates the evidence of drill rows; however, this location will remain in-process. Large patches of cheatgrass were observed within the location disturbance area. Russian thistle germination was observed throughout the disturbance area that was seeded. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards.

Inspection Photos
Location Name: STATE ANTELOPE #11-12
API: 05-123-24326



Photo 2. Photo taken from the entrance of the location, facing Northeast. Photo illustrates patches of cheatgrass observed within the location disturbance area.

Inspection Photos

Location Name: STATE ANTELOPE #11-12

API: 05-123-24326



Photo 3. Photo taken from the entrance of the location, facing East. See comments under Photo 2.

Inspection Photos
Location Name: STATE ANTELOPE #11-12
API: 05-123-24326



Photo 4. Photo taken from the former western production area, facing Northeast.
Photo illustrates a patch of Russian thistle.

Inspection Photos

Location Name: STATE ANTELOPE #11-12

API: 05-123-24326



Photo 5. Reference photo taken from the southeastern perimeter of the location, facing West.