

**Inspection Photo
McLin B20
API # 045-19383
Inspection # 689301297**



Location Photo #1,



Location Photo #2,



**Inspection Photo
McLin B20
API # 045-19383
Inspection # 689301297**



Location Photo #3, sign not legible on tank



Location Photo #4, Stained rock in containment

**Inspection Photo
McLin B20
API # 045-19383
Inspection # 689301297**



Location Photo #5, Stained rock in containment



Location Photo #6, Stained rock in containment

Inspection Photo
McLin B20
API # 045-19383
Inspection # 689301297



Location Photo #7, Stained rock in containment