

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/18/2018

Submitted Date:

06/18/2018

Document Number:

689301315**FIELD INSPECTION FORM**

Loc ID 335310 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|----------------|---|--|
| Elsener, Garrett | (303)-565-4600 | COGCC.inspections@caerus oilandgas.com | all Piceance inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 270272 | WELL | PR | 04/26/2004 | GW | 045-09513 | BENZEL 26-9A (I26NW) | PR |
| 270274 | WELL | PR | 05/11/2004 | GW | 045-09511 | BENZEL 26-10A (26NW) | PR |
| 270275 | WELL | PR | 04/10/2004 | GW | 045-09510 | BENZEL 25-12B (I26NW) | PR |
| 270311 | WELL | PR | 04/30/2004 | GW | 045-09524 | BENZEL 26-9C | PR |

General Comment:[Routine Field Inspection](#)

Location

| | | | |
|--------------------|--------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | | Date: | |

Overall Good: ☒

Emergency Contact Number:

Comment: 1-800-791-7691

Corrective Action:

Date:

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | OTHER | | |
| Comment: | Stained rock in tank battery containment, see attached photo | | |
| Corrective Action: | Properly treat or dispose of oily waste in accordance with Rule 907.e. | Date: | 07/18/2018 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Live stock gates | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|---------------------------------|-----|-------|-----------------|
| | | | corrective date |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pig Station | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Vertical Heated Separator | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | |
|--------------------|-----|-------|
| Type: Plunger Lift | # 4 | |
| Comment: | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| | | | | | |
|--------------------|---|----------|-----------|---------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CONDENSATE | 1 | 500 BBLs | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|-----------------------|--------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 270272 | Type: | WELL | API Number: | 045-09513 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 270274 | Type: | WELL | API Number: | 045-09511 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 270275 | Type: | WELL | API Number: | 045-09510 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| | | | | | | | | | |
| Facility ID: | 270311 | Type: | WELL | API Number: | 045-09524 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

Environmental

Spill/Remediation:

Comment:

Corrective
Action:

Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:

Wildlife Protection Devices (fired vessels):

YES

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|-------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Ditches | | | | | | |
| | | Compaction | | | | |
| | | Gravel | | | | |
| Berms | | | | | | |
| Sodding | | | | | | |
| Gradient Terraces | | | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------------|---|
| 689301316 | Inspection Photo 689301316 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4497806 |