

Inspection Photos

06/19/2018

Operator: ABILENE PERFECT ENERGY JV LLC -
10581

Location ID: 414589

Inspection Doc. Number: 682503512
Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: ABILENE PERFECT ENERGY JV LLC - 10581
Location ID: 414589



Photo 1: Photo of sign at location gate.



Photo 2: Photo taken from the south end of the location facing east. Photo shows what appears to be four (4) bundles of pipe stored on the southern interim areas. This is considered unused equipment not needed for production and needs to be removed from location.

Inspection Photos

Operator: ABILENE PERFECT ENERGY JV LLC - 10581

Location ID: 414589



Photo 3: Photo taken from the south end of the tank battery berm, facing east. Photo shows vegetation establishment on the berm. Vegetation compromises the integrity of the containment berms and needs to be removed.



Photo 4: Photo taken from the east end of the tank battery berm, facing northwest. Photo shows vegetation establishment on the berm. Vegetation compromises the integrity of the containment berms and needs to be removed.

Inspection Photos
Operator: ABILENE PERFECT ENERGY JV LLC - 10581
Location ID: 414589



Photo 5: Photo taken from the north end of the location, facing north. Photo shows vegetation establishment on the berm. Vegetation compromises the integrity of the containment berms and needs to be removed.



Photo 6: Photo taken from the west end of the tank battery. Photo shows that the manway cover has been removed from the tank. Photo also shows stained soils within berm.

Inspection Photos

Operator: ABILENE PERFECT ENERGY JV LLC - 10581

Location ID: 414589



Photo 7: Photo taken from the west end of the location. Photo shows 5 gallon bucket being used to collect chemicals from equipment. Photo also shows stained soils at base. Equipment needs to be repaired to prevent leaks, bucket needs to be removed and properly disposed or placed in containment.



Photo 8: See comments under photo 7.

Inspection Photos
Operator: ABILENE PERFECT ENERGY JV LLC - 10581
Location ID: 414589



Photo 9: Photo taken from the west end of the location, facing northwest. Photo of bucket and various trash debris that appears to have been blown onto the interim areas.



Photo 10: Photo taken from the southeast corner of the pump jack facing northwest. Photo shows numerous 5 gallon buckets with chemical and oil jugs found around the pump jack. Buckets need to be properly removed and disposed, or placed into containment. Photo also shows unused equipment that needs to be removed.

Inspection Photos
Operator: ABILENE PERFECT ENERGY JV LLC - 10581
Location ID: 414589



Photo 11: Photo taken from the east end of the pump, facing west. Photo shows unused equipment stored on location. Equipment is not need for production and needs to be removed.



Photo 12: Photo taken from the north end of the well, facing west. Photo shows oil stained soils requiring cleaning.

Inspection Photos
Operator: ABILENE PERFECT ENERGY JV LLC - 10581
Location ID: 414589



Photo 13: Photo taken from the west end of the location, facing west. Photo of various trash in the interim areas.



Photo 14: Photo taken from the west end of the location, facing south. Photo of various trash in the interim areas.

Inspection Photos
Operator: ABILENE PERFECT ENERGY JV LLC - 10581
Location ID: 414589



Photo 15: Photo taken from the north end of the location, facing north. Photo shows stained (E&P waste) soil piled on the north end of the location.



Photo 16: Photo taken from the north end of the location, facing east. Photo shows 5 gallon buckets with chemical outside of containment

Inspection Photos
Operator: ABILENE PERFECT ENERGY JV LLC - 10581
Location ID: 414589



Photo 17: Photo taken from then north end of the location, facing southwest. Photo shows unused equipment not needed for production. This needs to be removed.



Photo 18: Photo taken from the northeast end of the location, facing north. Photo of camper trailer being stored on the northern end of the location. This is not needed for production and needs to be removed. Additionally, these areas do not appear to be reasonably needed for production and needs to be reclaimed.

Inspection Photos

Operator: ABILENE PERFECT ENERGY JV LLC - 10581

Location ID: 414589



Photo 19: Photo taken from the east end of the location, facing south. Photo shows various unused equipment not needed for production being stored on location. This needs to be removed. Additionally, these areas do not appear to be reasonably needed for production and needs to be reclaimed.



Photo 20: Photo taken from the east end of the location, facing southwest. Photo shows various unused equipment not needed for production being stored on location. This needs to be removed. Additionally, these areas do not appear to be reasonably needed for production and needs to be reclaimed.

Inspection Photos

Operator: ABILENE PERFECT ENERGY JV LLC - 10581

Location ID: 414589



Photo 21: Photo taken from the east end of the location, facing east. Photo of straw wattles. This is considered debris and needs to be removed.



Photo 22: Photo taken from the northeast end of the location, facing north east. Photo shows what appears to be solar panels being stored on location. This is equipment not needed for production and needs to be removed. Additionally, these areas do not appear to be reasonably needed for production and needs to be reclaimed.

Inspection Photos

Operator: ABILENE PERFECT ENERGY JV LLC - 10581

Location ID: 414589



Photo 23: Photo taken from the northeast end of the location, facing north. Photo shows various unused equipment or trash debris not needed for production being stored on location. This needs to be removed. Additionally, these areas do not appear to be reasonably needed for production and needs to be reclaimed.



Photo 24: Photo taken from the north end of the location, facing west. Photo shows various unused equipment or trash debris not needed for production being stored on location. This needs to be removed. Additionally, these areas do not appear to be reasonably needed for production and needs to be reclaimed.

Inspection Photos
Operator: ABILENE PERFECT ENERGY JV LLC - 10581
Location ID: 414589



Photo 25: Photo taken from the north end of the location, facing west. Photo shows various unused equipment or trash debris not needed for production being stored on location. This needs to be removed. Additionally, these areas do not appear to be reasonably needed for production and needs to be reclaimed.



Photo 26: Photo taken from the north end of the camper trailer. Photo shows hose leading from the north end of the camper to a covered hole on the ground; Hose appears to be associated with the grey and/or waste water from the camper.

Inspection Photos
Operator: ABILENE PERFECT ENERGY JV LLC - 10581
Location ID: 414589



Photo 27: Continued from photo 26



Photo 28: Continued from photo 26. Photo of hole where hose from camper leads to.

Inspection Photos
Operator: ABILENE PERFECT ENERGY JV LLC - 10581
Location ID: 414589



Photo 29: Photo taken from the north end of the camper facing west. Photo shows numerous 5 gallon buckets with chemical. Buckets need to be properly removed and disposed, or placed into containment.



Photo 30: Continued from photo 29