



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern portion of the project area from the southwestern corner facing northward. Revegetation is progressing within outer reclamation areas with grasses such as Indian ricegrass (*Achnatherum hymenoides*), smooth brome (*Bromus inermis*), and sand dropseed (*Sporobolus cryptandrus*).



Photo 3. View of the eastern portion of the project area from the northeastern corner facing southward. Vegetation is dry and sparse.



Photo 4. View of liner debris and trash in the southeastern project area.



Photo 5. View of the southern portion of the project area from the southwestern edge facing southeastward.



Photo 6. View of Russian knapweed (*Rhaponticum repens*) infestation in the southern portion of the project area.