

Inspection Photos

06/19/2018

Operator: WIEPKING-FULLERTON ENERGY LLC -
96340

Location ID: 436744

Inspection Doc. Number: 682503516
Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: WIEPKING-FULLERTON ENERGY LLC - 96340
Location ID: 436744



Photo 1: Photo taken from the access road, facing northeast. Photo shows no additional work appears to have been conducted since the previous inspection; it appears a two-pronged ripper only cut through areas of the ruts within the road. Compaction alleviation does not appear to have been conducted in accordance to reclamation requirements. **Compaction concerns remain on access road.**



Photo 2: Photo taken from the access road, facing northeast. Photo shows inspector tested the access road for compaction concerns. Photo shows soils **OUTSIDE** the areas of the ruts, where a ripper **DID NOT** pass through, were difficult to penetrate; inspector was only able to easily penetrate the top couple inches of soil. Compaction concerns remain evident.

Inspection Photos
Operator: WIEPKING-FULLERTON ENERGY LLC - 96340
Location ID: 436744



Photo 3: Photo taken from the adjacent reference area. Photo shows inspector was able to easily penetrate the soils in the reference area.



Photo 4: Photo taken from the northern portion of the access road. Photo shows portion of access road where no reclamation activities appear to have been conducted; gravel remains on road, access road has not been re-contoured, re-graded or had compaction alleviation conducted.



06.19.2018 12:34

Photo 5: Photo taken from the area where the north section of access road joins the east/west ranch road, facing southwest. Photo shows portion of access road where no reclamation activities appear to have been conducted; gravel remains on road, access road has not been re-contoured, re-graded or had compaction alleviation conducted.