

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/20/2018

Submitted Date:

06/22/2018

Document Number:

680402951**FIELD INSPECTION FORM**
 Loc ID 314731 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100264Name of Operator: XTO ENERGY INCAddress: 21459 CR 5City: RIFLE State: CO Zip: 81650**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|----------------|-------------------------------|---------------------------------|
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| Dooling, Jessica | (970) 878-6800 | Jessica_Dooling@xtoenergy.com | Piceance Basin Field |
| Reid, Van | | Van_reid@xtoenergy.com | XTO Piceance and BOPCO Piceance |
| Browning, Chuck | 970-433-4139 | chuck.browning@state.co.us | Field Inspector |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------------|-------------|
| 229436 | WELL | TA | 03/01/2018 | DSPW | 103-07091 | U S A-PICEANCE CREEK 26-7G | AC |

General Comment:

Routine UIC inspection.

Location**Lease Road:**

| | | | |
|-------------------|--------|-------|--|
| Type | Access | | |
| comment: | | | |
| Corrective Action | | Date: | |
| Type | Main | | |
| comment: | | | |
| Corrective Action | | Date: | |

Overall Good: ☒**Signs/Marker:**

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | |
|--------------------|--|-------------|
| Comment: | | |
| Corrective Action: | | Date: _____ |

Overall Good: ☒**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|-----------------------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Injection wellhead inside housing | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|---------------------------|--|-------|-----------------|
| Type: Ancillary equipment | # 1 | | corrective date |
| Comment: | Propane tank with barricade. Solar panels and telemetry. | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 229436 Type: WELL API Number: 103-07091 Status: TA Insp. Status: AC**Underground Injection Control**

UIC Violation: _____ Maximum Injection Pressure: _____

UIC RoutineInj./Tube: Pressure or inches of Hg 82 Previous Test Pressure _____ MPP _____

(e.g. 30 psig or -30" Hg)

Inj Zone: WSTCATC: Pressure or inches of Hg 0 Previous Test Pressure _____ Last MIT: 07/17/2013Brhd: Pressure or inches of Hg 0 Previous Test Pressure _____ AnnMTReq: _____Comment: Routine UIC inspection. No active injection at time of inspection.
MIT due by 7/17/2018.

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|-----------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | Self Inspection | Pass | |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------------------|---|
| 680402971 | Inspection photos 6/20/2018 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4502796 |