

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/19/2018

Submitted Date:

06/22/2018

Document Number:

680303428**FIELD INSPECTION FORM**Loc ID 312151 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10380Name of Operator: BENCHMARK ENERGY LLCAddress: PO BOX 8747City: PRATT State: KS Zip: 67124**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Burn, Diana		diana.burn@state.co.us	
Sutphin, Dirk		dirk.sutphin@state.co.us	
Hickey, Mike		michael.hickey@state.co.us	
Andrews, Dave		david.andrews@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
219053	WELL	TA	01/01/1999	ERIW	075-05875	NW GRAYLIN (LOGAN J 12-2W) 2-W	TA

General Comment:

Bradenhead FIR - ODO Program - Benchmark Project - Pressure on well = 0.

Location

Lease Road:			
Type	Access		
comment:	Two track - grassland		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign laying on ground. Cattle grazing at wellhead, pushed sign over.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Satisfactory

Corrective Action: _____ Date: _____

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 0		
Comment:	No surface equipment on location.		
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	219053	Type:	WELL	API Number:	075-05875	Status:	TA	Insp. Status:	TA
BradenHead									
Comment: Pressure on well = 0.									
Corrective Action:									
Date:									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	In Process	Other	In Process			

Comment: No BMP's in use. Surface is grassland, some erosion on lease road (ruts), area at/around wellhead requiring reclamation.

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT