

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/22/2018

Submitted Date:

06/22/2018

Document Number:

691200216

FIELD INSPECTION FORM

Loc ID 332767 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

21 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Precup, Jim		james.precup@state.co.us	
Gomez, Jason		jason.gomez@state.co.us	
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275941	WELL	SI	10/01/2016	GW	123-22706	BOOTH N 25-25	SI
275969	WELL	PA	07/14/2017	OW	123-22709	BOOTH N 25-14	PA
275970	WELL	SI	10/01/2016	GW	123-22708	BOOTH N 25-13	SI

General Comment:

Location

Lease Road:			
Type	Access		
comment:	Access road to Booth N 25-25 (API# 05-123-22706), Booth N 25-13 (API# 05-123-22708) wellheads is adequate.		
Corrective ActionL		Date:	
Type	Main		
comment:	Main road to Booth N 25-25 (API# 05-123-22706), Booth N 25-13 (API# 05-123-22708) battery is adequate.		
Corrective ActionL		Date:	

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	IGNITOR/COMBUSTOR		
Comment:	ECD has barbed wire fencing.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Booth N 25-13 (API# 05-123-22708) has iron panel fencing.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Booth N 25-25 (API# 05-123-22706) has iron panel fencing.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Booth N 25-11 (API# 05-123-22680), Booth N 25-12 (API# 05-123-22681), Booth N 25-25 (API# 05-123-22706), Booth N 25-13 (API# 05-123-22708), battery has barbed-wire fencing.		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Booth N 25-11 (API# 05-123-22680), Booth N 25-12 (API# 05-123-22681), Booth N 25-25 (API# 05-123-22706), Booth N 25-13 (API# 05-123-22708) separators have barbed wire fencing.		
Corrective Action:		Date:	

Equipment:		corrective date
Type: Horizontal Heated Separator	# 2	

Comment:	East separator has 2 commingled wells. 1.) Booth N 25-25 (API# 05-123-22706) 2.) Booth N 25-13 (API# 05-123-22708)			
	West separator has 2 commingled wells. 1.) Booth N 25-11 (API# 05-123-22680) 2.) Booth N 25-12 (API# 05-123-22681)			
Corrective Action:			Date:	
Type: Plunger Lift	# 2			
Comment:				
Corrective Action:			Date:	
Type: Emission Control Device	# 1			
Comment:	ECD controls oil tanks VOCs			
Corrective Action:			Date:	
Type: Gas Meter Run	# 2			
Comment:				
Corrective Action:			Date:	
Type: Bird Protectors	# 3			
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment:	This centralized battery serves 3 locations (332767, 305227, 305228).				
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		40.366930,-104.846800
Comment:	This tank serves Booth N 25-25 (API# 05-123-22706), Booth N 25-13 (API# 05-123-22708) wells.				
Corrective Action:			Date:		

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity) 265 Bbls.	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	Shares berms with 300 Bbls. produced oil tank and produced H2O vaults.		
Corrective Action:		Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		

Comment:	This tank serves Booth N 25-11 (API# 05-123-22680), Booth N 25-12 (API# 05-123-22681) wells.		
Corrective Action:		Date:	

Paint

Condition	Adequate
-----------	----------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	Shares berms with 265 Bbls. produced oil tank and produced H2O vaults.		
Corrective Action:		Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	PBV CONCRETE		

Comment:	
Corrective Action:	
Date:	

Paint

Condition	
-----------	--

Other (Content)	
Other (Capacity) 48 Bbls.	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	Shares berms with produced oil tanks.		
Corrective Action:		Date:	

Venting:

Yes/No	NO
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 275941 Type: WELL API Number: 123-22706 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Comment: Bradenhead appears plumbed to surface.

Corrective Action: _____ Date: _____

Facility ID: 275969 Type: WELL API Number: 123-22709 Status: PA Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: This well has been P&A'd.

Corrective Action: _____ Date: _____

Facility ID: 275970 Type: WELL API Number: 123-22708 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Comment: Bradenhead appears plumbed to surface.

Corrective Action: _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691200217	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4503355