

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/23/2018

Submitted Date:

06/24/2018

Document Number:

688302099

FIELD INSPECTION FORM

Loc ID 437846 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 19160
Name of Operator: CONOCO PHILLIPS COMPANY
Address: P O BOX 2197
City: HOUSTON State: TX Zip: 77252-

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|----------------|-------------------------------------|------------------------|
| Dixon, Jennifer | (701) 264-2041 | jennifer.a.dixon@conocophillips.com | Regulatory Coordinator |
| ConocoPhillips | | COPColoradoReg@conocophillips.com | |
| Chesson, Bob | | robert.chesson@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------------------|-------------|
| 437851 | WELL | DG | 11/01/2018 | LO | 005-07228 | State La Plata 5-65 13-15 4AH | DG |
| 449152 | WELL | DG | 11/29/2017 | | 005-07259 | State La Plata 5-65 13-15 3DH | DG |

General Comment:

Inspected Facilities

Facility ID: 437851 Type: WELL API Number: 005-07228 Status: DG Insp. Status: DG

Facility ID: 449152 Type: WELL API Number: 005-07259 Status: DG Insp. Status: DG

Completion

Operation: Flowback

Date Flowback:

Contractor: Select

Comment: At approximately 5:30 pm on 6/22/2018 flowback was shut in for 4 hours due to gas sales line pop off release of ~5 gallons of condensate mist SW across pad and to the edge of the pad. Winds were strong at the time. Paraffin build up cased the ESD to load up. A drip pot was installed. COGCC Field Inspector was notified Friday night and the SLB to be notified the next day.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------------|---|
| 688302102 | ConocoPhillips State La Plata | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4503416 |