

Final Reclamation Inspection

June 19, 2018

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

API: 05-123-16156

Inspection Document #: 682403711

Weld County, CO

SWNW Section 29 T2N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SHAW #12-29A
API: 05-123-16156



Photo 1. Photo taken from a portion of the access road, facing East. Photo illustrates an area of pooled water just west of the well location. Staff could not inspect this area of the access road for ruts. Staff did not drive past this point during the inspection.



Photo 2. Photo taken from a portion of the northern access road, facing East. Appears a seeding attempt was performed by the evidence of drill rows. Operator may need to perform additional reclamation work as there did not appear to be uniform germination. Operator shall comply with Rule 1004 standards throughout all disturbance areas.

Inspection Photos
Location Name: SHAW #12-29A
API: 05-123-16156



Photo 3. Photo taken from a portion of the southern access road, facing West. See comments under Photo 2. Also, Kochia weeds were observed throughout portions of the disturbance area. Operator shall control and manage Kochia until the location meets Rule 1004 standards.



Photo 4. Photo taken from a portion of the southern access road, facing East. See comments under Photo 3.

Inspection Photos
Location Name: SHAW #12-29A
API: 05-123-16156



Photo 5. Photo taken just west of the well location, facing West. Photo illustrates Kochia rosette weeds (lower growing vegetation). See comments under Photo 3.



Photo 6. Photo taken just west of the well location, facing East. Photo illustrates Kochia rosette weeds (lower growing vegetation). See comments under Photo 3.

Inspection Photos
Location Name: SHAW #12-29A
API: 05-123-16156



Photo 7. Photo taken near the well location. Photo illustrates Musk thistle, a List B Colorado noxious weed. Operator shall control and manage all List B Colorado noxious weeds. Staff only observed a few Musk and Scotch thistle plants. Scotch thistle is also a List B Colorado noxious weed.



Photo 8. Photo taken from the well location, facing East. Photo illustrate a disturbance area from the well location and the removal of a flowline. Operator shall comply with Rule 1004 standards throughout all disturbance areas. No surface equipment was observed at the well location.

Inspection Photos
Location Name: SHAW #12-29A
API: 05-123-16156



Photo 9. Photo taken from a portion of the flowline disturbance area at the interaction of the access road, facing West. See comments under Photos 3 & 8.




Photo 10. Photo taken from a portion of the northern access road, facing West. See comments under Photos 3 & 8.

Inspection Photos
Location Name: SHAW #12-29A
API: 05-123-16156



Photo 11. Photo taken from the battery location. Battery location is still active a services another nearby well.



Photo 12. Photo taken from a portion of the southern access road, facing East. Per Rule 1002.e.(4), Operator shall minimize disturbances and shall not travel outside of the original access road boundary. Appears ruts were recently created. Operator shall repair ruts and shall comply with Rule 1004 standards.