

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/20/2018

Submitted Date:

06/26/2018

Document Number:

685304931**FIELD INSPECTION FORM**

Loc ID 325648 Inspector Name: St John, William (Cal) On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96735  
 Name of Operator: WILLIFORD RESOURCES, L.L.C.  
 Address: 6506 S LEWIS AVE STE 102  
 City: TULSA State: OK Zip: 74136

**Findings:**

17 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

| Contact Name    | Phone        | Email                        | Comment                               |
|-----------------|--------------|------------------------------|---------------------------------------|
| Callahan, Linda | 918-749-8828 | lcallahan3@swbell.net        | <a href="#">SW Inspection Reports</a> |
| Stevens, Glenn  | 970-749-0192 | glennstevens@centurylink.net | <a href="#">SW Inspection Reports</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 215165      | WELL | PR     | 06/01/2017  | GW         | 067-06770 | SPRING HOLLOW MAC 3 | PR          |

**General Comment:**

[Inspection completed as routine inspection requirement.](#)

[This inspection does not alleviate requirement to complete any open corrective actions from previous inspections.](#)

[See link at end of report for path to downloadable pictures.](#)

| Location   |   |        |                 |
|--|---|--------|-----------------|
| <b>Lease Road:</b>                                     |   |        |                 |
| Type   | Access  |        |                 |
| comment:   | Dirt two track access road. Road will require maintenance.            |        |                 |
| Corrective ActionL                                     |   |        | Date:           |
| Overall Good: <input type="checkbox"/>                 |   |        |                 |
| <b>Signs/Marker:</b>                                   |   |        |                 |
| Type   | WELLHEAD  |        |                 |
| Comment:   | Framed metal sign.  |        |                 |
| Corrective Action:                                     |   |        | Date:           |
| Emergency Contact Number:                              |   |        |                 |
| Comment:   | Operator contact information posted on wellhead sign.                 |        |                 |
| Corrective Action:                                     |   |        | Date: _____     |
| <b>Good Housekeeping:</b>                              |   |        |                 |
| Type   | OTHER   |        |                 |
| Comment:   | Impacted soil pile at wellhead. Less than a 5 gallon bucket clean up. |        |                 |
| Corrective Action:                                     |   |        | Date:           |
| Overall Good: <input type="checkbox"/>                 |   |        |                 |
| <b>Spills:</b>   |   |        |                 |
| Type   | Area  | Volume |                 |
| In Containment: No                                     |   |        |                 |
| Comment:   |   |        |                 |
| <input type="checkbox"/> Multiple Spills and Releases? |   |        |                 |
| <b>Fencing/:</b>                                       |   |        |                 |
| Type   | PUMP JACK   |        |                 |
| Comment:   | Steel safety rails.   |        |                 |
| Corrective Action:                                     |   |        | Date:           |
| <b>Equipment:</b>                                      |   |        |                 |
| Type: Pump Jack  | # 1   |        | corrective date |
| Comment:   |   |        |                 |
| Corrective Action:                                     |   |        | Date:           |
| Type: Ancillary equipment                              | # 1   |        |                 |
| Comment:   | Wellhead.   |        |                 |
| Corrective Action:                                     |   |        | Date:           |
| Type: Deadman # & Marked                               | # 4   |        |                 |
| Comment:   |   |        |                 |
| Corrective Action:                                     |   |        | Date:           |
| Type: Flow Line  | # 5   |        |                 |

|                    |  |  |       |
|--------------------|--|--|-------|
| Comment:           | In use - 3" steel line from wellhead tubing to remote tank battery on CR 129.<br>In use - 1" steel gas line from wellhead casing to gas knock out. Line is then split and one leg is to supply gas knock out and the other leg goes into ground. (C) point unknown (possible gas gathering).<br>Unused - 1" steel line on W side of location by access road. Line has valve and plug installed. (B) point unknown. |  | Date: |
| Corrective Action: |  |  | Date: |
| Type: Prime Mover  | # 1  |  |       |
| Comment:           | Natural gas motor.   |  |       |
| Corrective Action: |  |  | Date: |
| Type: Other        | # 1  |  |       |
| Comment:           | 55 gallon drum on spill prevention.  |  |       |
| Corrective Action: |  |  | Date: |

**Tanks and Berms:**

| Contents           | #                             | Capacity | Type      | Tank ID | SE GPS |
|--------------------|-------------------------------|----------|-----------|---------|--------|
| CRUDE OIL          | 2                             | 300 BBLs | STEEL AST |         |        |
| Comment:           | Remote battery located CR 129 |          |           |         |        |
| Corrective Action: |                               |          |           |         | Date:  |

Paint

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

Berms

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |    |       |
|--------------------|----|-------|
| Yes/No             | NO |       |
| Comment:           |    |       |
| Corrective Action: |    | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

**Inspected Facilities**

Facility ID: 215165 Type: WELL API Number: 067-06770 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: Revegetation of interim reclamation area is progressing with mixed vegetation.

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_  
 1003c. Compacted areas have been cross ripped? \_\_\_\_\_  
 1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_  
 Cuttings management: \_\_\_\_\_  
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_  
 Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT  
 TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_  
 TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_  
 TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_  
 VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment  |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|--|
| Compaction       | Pass            | Compaction              | Pass                  | Material Handling And Spill Prevention | Pass                     | 55 gallon condensate barrel on spill prevention. |
|                  |                 | Culverts                | Pass                  |  |                          |  |

Comment: [Stormwater BMPs appear to be functioning at time of inspection.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description        | URL                                     |
|--------------|--------------------|---|
| 685304953    | Inspection photos. | <a href="#">Inspection Template.pdf</a> |