

Inspection Photo
Clough RWF 27-11-6S-94W
API # 045-06573
Inspection # 689301390



Location Photo #1



Location Photo #2, missing wellhead sign