

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/26/2018

Submitted Date:

06/26/2018

Document Number:

689301390**FIELD INSPECTION FORM**
 Loc ID 430758 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10550Name of Operator: MUSTANG RESOURCES LLCAddress: 1660 LINCOLN STREET SUITE 1450City: DENVER State: CO Zip: 80264**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|--------------------------------|---------|
| Lemon, Deb | | dlemon@mustangresourcesllc.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 210815 | WELL | PR | 03/01/2018 | GW | 045-06573 | CLOUGH 27-11-6S-94W | SI |

General Comment:[Routine Field Inspection](#)

Location

| | | | |
|--------------------|--------|-------|--|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | L | Date: | |

Overall Good: ☒

| | | | |
|----------------------|---|-------|------------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Sign or label not posted at Wellhead | | |
| Corrective Action: | Install sign to comply with Rule 210.d. | Date: | 08/26/2018 |

Emergency Contact Number:

Comment: 1-888-291-8588

Corrective Action:

Date:

Good Housekeeping:

| | | | |
|--------------------|--------|-------|--|
| Type | TRASH | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WEEDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | DEBRIS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Overall Good: ☒

| | | | | |
|----------------|------|--------|--|--|
| Spills: | | | | |
| Type | Area | Volume | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|--------------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Deadman # & Marked | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|----------|----|--|--|
| Yes/No | NO | | |
| Comment: | | | |

| | | | |
|--------------------|--|-------|--|
| Corrective Action: | | Date: | |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected FacilitiesFacility ID: 210815 Type: WELL API Number: 045-06573 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: EQUIPMENT ONSITEComment: Well shut in at time of inspectionCorrective Action: Date:

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Culverts | | | | |
| | | Compaction | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------------------|---|
| 689301391 | Inspection Photo 689301391 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4507547 |