

FORM  
INSPRev  
X/15

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/26/2018

Submitted Date:

06/27/2018

Document Number:

685304962**FIELD INSPECTION FORM**

Loc ID 334050 Inspector Name: St John, William (Cal) On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10559  
 Name of Operator: SOUTHLAND ROYALTY COMPANY LLC  
 Address: 400 WEST 7TH STREET  
 City: FORT WORTH State: TX Zip: 76102

**Findings:**

28 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Hampton, John	505-330-4377	jhampton@ctfieldsvcs.com	<a href="#">SW Inspection Reports</a>
Howe, Mike		MHowe@ctfieldsvcs.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277144	WELL	PR	04/14/2005	GW	007-06211	CANDELARIA 32-5 8-2	PR
298154	WELL	PR	01/19/2009	GW	007-06263	CANDELARIA 32-5 8-4	PR
298809	WELL	PR		GW	007-06268	DUNGAN 32-5 5-5	PR

**General Comment:**

[Inspection completed as routine inspection requirement.](#)

[This inspection does not alleviate requirement to complete any open corrective actions from previous inspections.](#)

[See link at end of report for path to downloadable pictures.](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Dirt and gravel access road.		
Corrective ActionL			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	Labels directly on containers.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Framed metal sign at wellhead.		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Operator contact information posted on wellhead sign.		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Chain link topped with barb wire.		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Steel mesh safety barrier.		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Steel safety rails.		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 3		
Comment:	Telemetry equipment.		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Chemical tank and pump on spill prevention.		
Corrective Action:			Date:

Type: Bird Protectors	# 5		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Metal shed with water transfer equipment.		
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Chemical tank and pump on spill prevention (tank battery).		
Corrective Action:			Date:
Type: Deadman # & Marked	# 6		
Comment:	Anchor marker is down and needs to be repaired.		
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	Wellhead.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electrical supply equipment.		
Corrective Action:			Date:
Type: Flow Line	# 3		
Comment:	<p>8-2                      In use - 2" steel line from wellhead casing and tubing to separator inlet. All points co-located.                      In use - 6" steel line from separator outlet to gas meter inlet. All points co-located.                      Unused - 2" steel line from wellhead to separator. Valves closed, line plugged, tagged, and locked out.</p>		
Corrective Action:			Date:
Type: Pump Jack	# 3		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	Electrical control equipment.		
Corrective Action:			Date:
Type: Flow Line	# 3		
Comment:	<p>8-4                      In use - 2" steel line from wellhead casing and tubing to separator inlet. All points co-located.                      In use - 2" steel line from wellhead casing and tubing to separator inlet. All points co-located.                      In use - 6: steel line from separator outlet to gas meter inlet. Off location.                      In use - 1" steel supply gas line from separator outlet to wellhead. All points co-located.</p>		
Corrective Action:			Date:
Type: Vertical Heated Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 3		

Comment:	<p>5-5                  In use - 2" steel line from wellhead casing and tubing to separator inlet. All points co-located.                  In use - 6" steel line from separator outlet to gas meter inlet. Off location                  Unused - 2" steel line from wellhead to separator. Valves are closed, line is plugged, tagged, and locked out. All points co-located.                  Unused - 1" steel line from separator to wellhead. Valves closed, line is plugged, tagged, and locked out. All points co-located.</p>		Date:
Corrective Action:			Date:
Type: Prime Mover	# 3		
Comment:	Electric motor.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLs	HEATED STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 277144 Type: WELL API Number: 007-06211 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR.

Corrective Action:

Date:

Facility ID: 298154 Type: WELL API Number: 007-06263 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR.

Corrective Action:

Date:

Facility ID: 298809 Type: WELL API Number: 007-06268 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR.

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: Revegetation of interim reclamation area is progressing with mixed vegetation.

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment

Corrective Action

Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment:

Corrective Action:

Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location  Multi-Well Location

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Compaction	Pass	Ditches	Pass			
Ditches	Pass	Gravel	Pass			
Sediment Traps	Pass					
Retention Ponds	Pass					
Berms	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Chemical tanks on spill prevention.

Comment: [Stormwater BMPs appear to be functioning at time of inspection.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685304985	Inspection photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4508718">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4508718</a>