

Inspection Photos

06/29/2018

Operator: ST CROIX OPERATING INC # 81490

Location ID: 455594

Inspection Doc. Number: 682503521

Washington County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: ST CROIX OPERATING INC # 81490
Location ID: 455594



Photo 1: Photo taken from the east end of the location, facing south. Photo shows equipment has been brought on location in preparation for drilling activities. Photo shows no soil salvage has been conducted on location. Photo also show no perimeter stormwater and sediment controls have been implemented.



Photo 2: Photo taken from the east end of the location, facing southwest. Photo shows equipment has been brought on location in preparation for drilling activities. Photo shows no soil salvage has been conducted on location. Photo also show no perimeter stormwater and sediment controls have been implemented.

Inspection Photos
Operator: ST CROIX OPERATING INC # 81490
Location ID: 455594



Photo 3: Photo taken from the east end of the location, facing northwest. Photo shows equipment has been brought on location in preparation for drilling activities. Photo shows no soil salvage has been conducted on location. Photo also show no perimeter stormwater and sediment controls have been implemented.



Photo 4: Photo taken from the east end of the location, facing north. Photo shows equipment has been brought on location in preparation for drilling activities. Photo shows no soil salvage has been conducted on location. Photo also show no perimeter stormwater and sediment controls have been implemented.

Inspection Photos
Operator: ST CROIX OPERATING INC # 81490
Location ID: 455594



Photo 5: Photo taken from the southeast end of the location, facing west. Photo shows equipment has been brought on location in preparation for drilling activities. Photo shows no soil salvage has been conducted on location. Photo also show no perimeter stormwater and sediment controls have been implemented.



Photo 6: Photo taken from the southeast end of the location, facing north. Photo shows equipment has been brought on location in preparation for drilling activities. Photo shows no soil salvage has been conducted on location. Photo also show no perimeter stormwater and sediment controls have been implemented.

Inspection Photos
Operator: ST CROIX OPERATING INC # 81490
Location ID: 455594



Photo 7: Photo taken from the south end of the location, facing west. Photo shows equipment has been brought on location in preparation for drilling activities. Photo shows no soil salvage has been conducted on location. Photo also show no perimeter stormwater and sediment controls have been implemented.



Photo 8: Photo taken from the south end of the location, facing north. Photo shows equipment has been brought on location in preparation for drilling activities. Photo shows no soil salvage has been conducted on location. Photo also show no perimeter stormwater and sediment controls have been implemented.

Inspection Photos
Operator: ST CROIX OPERATING INC # 81490
Location ID: 455594



Photo 9: Photo taken from the south end of the location, facing east. Photo shows equipment has been brought on location in preparation for drilling activities. Photo shows no soil salvage has been conducted on location. Photo also show no perimeter stormwater and sediment controls have been implemented.



Photo 10: Photo taken from the center of the location, facing east. Photo shows equipment has been brought on location in preparation for drilling activities. Photo shows no soil salvage has been conducted on location.

Inspection Photos
Operator: ST CROIX OPERATING INC # 81490
Location ID: 455594



Photo 11: Photo taken from the north end of the location, facing east. Photo shows equipment has been brought on location in preparations for drilling activities. Photo shows no soil salvage has been conducted on location. Photo also show no perimeter stormwater and sediment controls have been implemented.



Photo 12: Photo taken from the east of the location, facing west. Photo of access road.

Inspection Photos
Operator: ST CROIX OPERATING INC # 81490
Location ID: 455594



Photo 13: Photo taken from the east of the location, facing north. Photo of access road. Though location resides in cropland, access road travels across non-cropland.



Photo 14: Photo of the vegetation adjacent to the North/South traveling section of the access road. Photo of shows road travels through non-crop grassland.



Photo 15: Photo taken from a the farmstead to the northeast of the location. Photo shows operator appears to be storing equipment on the property.