



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern portion of the project area from the northeastern corner facing westward. Revegetation is sparse in portions, and progressing in other areas with grasses such as western wheatgrass (*Pascoopyrum smithii*) and smooth brome (*Bromus inermis*).



Photo 3. View of Russian knapweed (*Rhaponticum repens*) infestation along the eastern edge of the project area.



Photo 4. View of area where rilling is occurring from stormwater runoff from the well pad, along the northwestern edge of the project area.



Photos 5 and 6. View of black plastic debris within the interim reclamation areas.