

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/01/2018

Submitted Date:

06/29/2018

Document Number:

688800178

**FIELD INSPECTION FORM**

Loc ID 334324 Inspector Name: Hughes, Jim On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 5  
Name of Operator: COLORADO OIL & GAS CONSERVATION  
Address: 1120 LINCOLN ST SUITE 801  
City: DENVER State: CO Zip: 80203

**Findings:**

7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267696	WELL	AC	06/15/2015	OBW	067-08801	MONITOR WELL 35-7-8-1	EI
267858	WELL	AC	06/15/2015	OBW	067-08811	MONITOR WELL 35-7-8-2	EI

**General Comment:**

On June 1, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the COGCC Monitor Well #35-7-8-1 and 35-7-8-2 (SFTC MWs #1 and #2). For the most recent field inspection report of this facility, please refer to document #674901736.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Signs mounted to protective cages around well heads.		
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
Comment:	Posted on sign mounted to metal shack.		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	4 x 4 x 4' expanded metal and angle iron protective cages around well heads.		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	In-Situ data loggers.		
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 267696 Type: WELL API Number: 067-08801 Status: AC Insp. Status: EI

Facility ID: 267858 Type: WELL API Number: 067-08811 Status: AC Insp. Status: EI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
On June 1, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the COGCC Monitor Well #35-7-8-1 and 35-7-8-2 (SFTC MWs #1 and #2). For the most recent field inspection report of this facility, please refer to document #674901736. During this field inspection, eight desiccant packets and one Desi-tube were replaced.	hughesj	06/29/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800179	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4511221">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4511221</a>