

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/25/2018

Submitted Date:

06/25/2018

Document Number:

689301380**FIELD INSPECTION FORM**

Loc ID 324014 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|--------------|------------------------|----------------------------------------|
| Aaron, Axelson | 230-0926 | aaxelson@vnrenergy.com | Sr. Production Foreman |
| Ghan, Scott | 970-744-8128 | sghan@vnrenergy.com | SR. EH&S |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------------|-------------|
| 211491 | WELL | PR | 08/08/2000 | GW | 045-07251 | GIBSON GULCH UNIT 15-30 D | PR |

General Comment:[Routine Field Inspection](#)

Location**Lease Road:**

| | | | |
|-------------------|--------|-------|--|
| Type | Access | | |
| comment: | | | |
| Corrective Action | L | Date: | |

Overall Good: ☒**Emergency Contact Number:**

| | | |
|--------------------|----------------|-------|
| Comment: | 1-800-921-8252 | |
| Corrective Action: | | Date: |

Good Housekeeping:

| | | | |
|--------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|------------|
| Type | WEEDS | | |
| Comment: | Noxious weeds including (species) observed in (geographic area of by equipment) part of location. Invasive non-native weeds located (area of location). See Photo | | |
| Corrective Action: | Comply with the 1003. f rule | Date: | 06/30/2018 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|-----------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Livestock gates | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|--------------------|-----|-------|-----------------|
| Type: Plunger Lift | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|-------------------------|-------|--|
| Yes/No | YES | | |
| Comment: | Bradenhead open to vent | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------------------------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 211491 | Type: | WELL | API Number: | 045-07251 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | Well Producing on plunger lift | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

| Environmental | |
|-----------------------------------|----------------------------------------------|
| Spill/Remediation: | |
| Comment: | |
| Corrective Action: | Date: |
| Emission Control Burner (ECB): NO | |
| Comment: | |
| Pilot: | Wildlife Protection Devices (fired vessels): |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | Compaction | | | | |
| | | Ditches | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 401684899 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4504666 |
| 689301381 | Inspection Photo 689301381 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4504658 |