

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/26/2018

Submitted Date:

06/26/2018

Document Number:

689301394

**FIELD INSPECTION FORM**

Loc ID 324161 Inspector Name: Holtz, Darin On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 7 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Rocky, TEP		COGCCInspectionReports@terraep.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260222	WELL	PR	08/08/2002	GW	045-07835	CLOUGH RMV 226-27	PR

**General Comment:**

[Serviced by facilities ID 260223](#)  
Routine Field Inspection

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

<b>Emergency Contact Number:</b>			
Comment:	1-970-285-9377		
Corrective Action:			Date:

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:
Type	TRASH		
Comment:			
Corrective Action:			Date:
Type	WEEDS		
Comment:			
Corrective Action:			Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Barbed wire fence		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Hog Panel fencing		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Chemical unit at Wellhead		
Corrective Action:			Date:

Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 260222 Type: WELL API Number: 045-07835 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Well Producing on plunger lift](#)

Corrective Action:

Date:

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:  Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Compaction						
Gravel						
		Culverts				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689301395	Inspection Photo 689301395	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4507556">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4507556</a>