



**Photo 1. View of the project area from the southwestern corner facing center.**





**Photo 2. View of the western cut-slope from the southwestern corner facing northward. Wattles are newly installed and rilling identified in earlier inspection is graded. Successful revegetation will help stabilize the slope.**





**Photo 3. View of the eastern portion of the project area from the northeastern corner facing southward.**





**Photo 4. View of cobble run-down in the eastern portion of the project area. Appears to be functioning at this time.**