



Photo 1. View of the project area from the eastern corner facing center.



Photo 2. View of the eastern portion of the project area from the eastern corner facing from the southwestern corner facing southwestward. Revegetation is progressing with grasses such as intermediate wheatgrass (*Thinopyron intermedium*), western wheatgrass (*Pascopyrum smithii*), and sand dropseed (*Sporobolus cryptandrus*).



Photo 3. View of the southwestern portion of the project area from the southwestern corner facing southeastward.



Photo 4. View of cobble run-down in the eastern portion of the project area. Appears to be functioning at this time.



Photo 5. View of erosional channel approximately 2 feet wide and 2.5 feet deep in the eastern portion of the project area that needs stabilization.