



Photo 1. View of the project area from the southeastern corner facing center. Project area is re-graded and expanded.



Photo 2. View of the southern portion of the project area from the southeastern corner facing westward. Run-on controls and stabilization measures are needed on these slopes until revegetation is achieved.



Photo 3. View of the portion of the project area from the southeastern corner facing northward. Berms and wattles in place. Erosion needs to be monitored until stabilization with vegetation is achieved.



Photo 4. View of well pad drainage outlet armored with rock. Appears to be functioning.



Photo 5. View of the northern portion of the project area from the well pad entrance facing eastward.