

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/03/2018

Submitted Date:

07/05/2018

Document Number:

689401441**FIELD INSPECTION FORM**Loc ID 312548 Inspector Name: CONKLIN, CURTIS On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Graves, Jim	(970) 858-8550	mrinc20@qwestoffice.net	Operation Manager
O'Hare, Mickey	(970) 563-4000/ (719) 429-3529	amohare@maralexinc.com	All Inspections
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer
Reid, Jordan	(970) 563-4000	maralextechjr@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221891	WELL	PR	03/01/2018	GW	077-08493	USA 1-18 JC	PR

General Comment:

This is a routine field inspection, any corrective actions not addressed from previous inspections are still applicable. This well is not listed in the AOC 1V-609

LocationOverall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Tank sign is not legible. See attached photo.		
Corrective Action:	Install sign to comply with rule 210	Date:	11/03/2018
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Posted Emergency Contact Number 1-970-585-8550

Corrective Action:

Date:

Good Housekeeping:

Type	OTHER		
Comment:	Vegetation and vegetation debris in tank containment and around equipment.		
Corrective Action:	Remove to comply with Rule 603.f	Date:	11/03/2018

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		HEATED STEEL AST		,
Comment: See sign section of inspection.					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment: See housekeeping section of inspection.				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

--

Inspected Facilities				
Facility ID: 221891	Type: WELL	API Number: 077-08493	Status: PR	Insp. Status: PR
Producing Well				
Comment:	PR at time of inspection			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Stormwater erosion appears to be controlled on the location at this time.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Type: Evaporation

Lined: NO

Pit ID:

Lat:

Long:

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date: c

Fencing:

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment: No Facility ID for second pit on location.

Corrective Action

Submit an eForm 15 Pit Report to update COGCC records with current information.

Date: 11/03/2018

Type: Evaporation

Lined: NO

Pit ID: 112451

Lat: 39.271180

Long: -108.372942

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date: c

Fencing:

Fencing Type: Livestock

Fencing Condition: Adequate

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition: _____

Inspector Name: CONKLIN, CURTIS

Comment:		Date:
Corrective Action		
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard:
Comment:		Date:
Corrective Action		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689401442	USA 1-18 JC Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4514935