

Inspection Photos
Location Name: McCallum Unit 100
API: 05-057-06187



Photo 1. Overview of location taken at entrance facing northwest.



Photo 2. No current operator information or emergency contact information on wellhead sign.

Inspection Photos
Location Name: McCallum Unit 100
API: 05-057-06187



Photo 3. Stained soil at wellhead. Lube oil stored without secondary containment.



Photo 4. Sediment migration across lease road with slope.

Inspection Photos
Location Name: McCallum Unit 100
API: 05-057-06187



Photo 5. Sediment migration onto lease road.



Photo 6. Sediment migration off lease road.