

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/06/2018

Submitted Date:

07/08/2018

Document Number:

688302177**FIELD INSPECTION FORM**Loc ID 317243 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**23 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name   | Phone          | Email                   | Comment |
|----------------|----------------|-------------------------|---------|
| Fritzler, Gene | (970) 867-9388 | gfritzler@bresnan.net   |         |
| Quint, Craig   |                | craig.quint@state.co.us |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 237370      | WELL | PR     | 08/15/2006  | OW         | 121-09871 | CRONK 1       | PR          |

**General Comment:**2018 Snapshot/High Priority Well Inspection

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | CONTAINERS           |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             | new sign             |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             | new sign             |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment: 970-867-1268

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | OTHER   |       |            |
| Comment:           | Crude oil tank valve teak, in containment.  |       |            |
| Corrective Action: | Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. | Date: | 08/10/2018 |

Overall Good: ☐

|  |      |        |  |
|--|------|--------|--|
| <b>Spills:</b>   |      |        |  |
| Type   | Area | Volume |  |
| In Containment: No                                     |      |        |  |
| Comment: _____   |      |        |  |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |  |

|                    |                    |       |  |
|--------------------|--------------------|-------|--|
| <b>Fencing/:</b>   |                    |       |  |
| Type               | WELLHEAD           |       |  |
| Comment:           | cattle wire panels |       |  |
| Corrective Action: |                    | Date: |  |

|                               |              |       |                 |
|-------------------------------|--------------|-------|-----------------|
| <b>Equipment:</b>             |              |       | corrective date |
| Type: Vertical Heater Treater | # 1          |       |                 |
| Comment:                      | shed, bermed |       |                 |
| Corrective Action:            |              | Date: |                 |
| Type: Deadman # & Marked      | # 4          |       |                 |
| Comment:                      |              |       |                 |

|                       |   |       |  |
|-----------------------|---|-------|--|
| Corrective Action:    |   | Date: |  |
| Type: FWKO            | # 1                                       |       |  |
| Comment:              | 340 bbls, bermed                          |       |  |
| Corrective Action:    |   | Date: |  |
| Type: Bird Protectors | # 8                                       |       |  |
| Comment:              |   |       |  |
| Corrective Action:    |   | Date: |  |
| Type: Prime Mover     | # 1                                       |       |  |
| Comment:              | electric motor, electric panel, REA poles |       |  |
| Corrective Action:    |   | Date: |  |
| Type: Prime Mover     | # 1                                       |       |  |
| Comment:              |   |       |  |
| Corrective Action:    |   | Date: |  |

**Tanks and Berms:**

| Contents           | #                    | Capacity | Type     | Tank ID | SE GPS |
|--------------------|----------------------|----------|----------|---------|--------|
| PRODUCED WATER     | 1                    | 200 BBLS | Open Top |         | ,      |
| Comment:           | metal net, skim tank |          |          |         |        |
| Corrective Action: |                      |          |          |         | Date:  |

**Paint**

|                  |  |
|------------------|--|
| Condition        |  |
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

| Type               | Capacity  | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|---|---------------------|---------------------|-------------|
|                    |   |                     |                     |             |
| Comment:           | Located next to 750 bbl open top tank, needs berms. |                     |                     |             |
| Corrective Action: |   |                     |                     | Date:       |

| Contents           | #      | Capacity | Type     | Tank ID | SE GPS |
|--------------------|--------|----------|----------|---------|--------|
| PRODUCED WATER     | 1      | OTHER    | Open Top |         | ,      |
| Comment:           | netted |          |          |         |        |
| Corrective Action: |        |          |          |         | Date:  |

**Paint**

|                  |          |
|------------------|----------|
| Condition        |          |
| Other (Content)  |          |
| Other (Capacity) | 750 bbls |
| Other (Type)     |          |

**Berms**

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
|      |          |                     |                     |             |

|                    |          |   |                     |             |        |                  |  |
|--------------------|----------|---|---------------------|-------------|--------|------------------|--|
| Comment:           |          | No berms  |                     |             |        |                  |  |
| Corrective Action: |          | Install berms around produced water tanks at wellhead |                     |             |        | Date: 08/10/2018 |  |
| Contents           | #        | Capacity  | Type                | Tank ID     | SE GPS |                  |  |
| CRUDE OIL          | 1        | 300 BBLS  | STEEL AST           |             | ,      |                  |  |
| Comment:           |          | 300 BBL green tank near wellhead is empty             |                     |             |        |                  |  |
| Corrective Action: |          |   |                     |             |        | Date:            |  |
| <u>Paint</u>       |          |   |                     |             |        |                  |  |
| Condition          |          |   |                     |             |        |                  |  |
| Other (Content)    |          |   |                     |             |        |                  |  |
| Other (Capacity)   |          |   |                     |             |        |                  |  |
| Other (Type)       |          |   |                     |             |        |                  |  |
| <u>Berms</u>       |          |   |                     |             |        |                  |  |
| Type               | Capacity | Permeability (Wall)                                   | Permeability (Base) | Maintenance |        |                  |  |
|                    |          |   |                     |             |        |                  |  |
| Comment:           |          |   |                     |             |        |                  |  |
| Corrective Action: |          |   |                     |             |        | Date:            |  |
| Contents           | #        | Capacity  | Type                | Tank ID     | SE GPS |                  |  |
| PRODUCED WATER     | 1        | 200 BBLS  | PBV STEEL           |             | ,      |                  |  |
| Comment:           |          |   |                     |             |        |                  |  |
| Corrective Action: |          |   |                     |             |        | Date:            |  |
| <u>Paint</u>       |          |   |                     |             |        |                  |  |
| Condition          |          |   |                     |             |        |                  |  |
| Other (Content)    |          |   |                     |             |        |                  |  |
| Other (Capacity)   |          |   |                     |             |        |                  |  |
| Other (Type)       |          |   |                     |             |        |                  |  |
| <u>Berms</u>       |          |   |                     |             |        |                  |  |
| Type               | Capacity | Permeability (Wall)                                   | Permeability (Base) | Maintenance |        |                  |  |
| Earth              |          |   |                     |             |        |                  |  |
| Comment:           |          | maintain berms  |                     |             |        |                  |  |
| Corrective Action: |          |   |                     |             |        | Date:            |  |
| Contents           | #        | Capacity  | Type                | Tank ID     | SE GPS |                  |  |
| PRODUCED WATER     | 1        | 200 BBLS  | PBV FIBERGLASS      |             | ,      |                  |  |
| Comment:           |          |   |                     |             |        |                  |  |
| Corrective Action: |          |   |                     |             |        | Date:            |  |
| <u>Paint</u>       |          |   |                     |             |        |                  |  |
| Condition          |          |   |                     |             |        |                  |  |
| Other (Content)    |          |   |                     |             |        |                  |  |
| Other (Capacity)   |          |   |                     |             |        |                  |  |
| Other (Type)       |          |   |                     |             |        |                  |  |
| <u>Berms</u>       |          |   |                     |             |        |                  |  |

|                    |                 |                     |                     |             |        |
|--------------------|-----------------|---------------------|---------------------|-------------|--------|
| Type               | Capacity        | Permeability (Wall) | Permeability (Base) | Maintenance |        |
| Earth              |                 |                     |                     |             |        |
| Comment:           | Maintain berms. |                     |                     |             |        |
| Corrective Action: |                 |                     |                     |             | Date:  |
| Contents           | #               | Capacity            | Type                | Tank ID     | SE GPS |
| CRUDE OIL          | 2               | 400 BBLS            | STEEL AST           |             | ,      |
| Comment:           |                 |                     |                     |             |        |
| Corrective Action: |                 |                     |                     |             | Date:  |
| <b>Paint</b>       |                 |                     |                     |             |        |
| Condition          |                 |                     |                     |             |        |
| Other (Content)    |                 |                     |                     |             |        |
| Other (Capacity)   |                 |                     |                     |             |        |
| Other (Type)       |                 |                     |                     |             |        |
| <b>Berms</b>       |                 |                     |                     |             |        |
| Type               | Capacity        | Permeability (Wall) | Permeability (Base) | Maintenance |        |
|                    |                 |                     |                     |             |        |
| Comment:           |                 |                     |                     |             |        |
| Corrective Action: |                 |                     |                     |             | Date:  |
| <b>Venting:</b>    |                 |                     |                     |             |        |
| Yes/No             | NO              |                     |                     |             |        |
| Comment:           |                 |                     |                     |             |        |
| Corrective Action: |                 |                     |                     |             | Date:  |
| <b>Flaring:</b>    |                 |                     |                     |             |        |
| Type               |                 |                     |                     |             |        |
| Comment:           |                 |                     |                     |             |        |
| Corrective Action: |                 |                     |                     |             | Date:  |

### Location Construction

Location ID: 237370 CDP: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

#### Form 2A COAs:

**Comment:** No COAs.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

#### Wildlife BMPs:

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Corrective Action:** \_\_\_\_\_

Date: \_\_\_\_\_

#### On Site Inspection (305):

##### Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

##### Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

##### LGD Contact Information:

Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Agreed to Attend: \_\_\_\_\_

##### Summary of Landowner Issues:

\_\_\_\_\_

##### Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

##### Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

| Inspected Facilities |   |       |      |             |           |         |    |               |    |
|----------------------|---|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 237370  | Type: | WELL | API Number: | 121-09871 | Status: | PR | Insp. Status: | PR |
| Producing Well       |   |       |      |             |           |         |    |               |    |
| Comment:             | PR. Dec 2017 production last reported to COGCC database. Update production (Form 7s). |       |      |             |           |         |    |               |    |
| Corrective Action:   |   |       |      |             |           |         |    | Date:         |    |

|  |  |  |  |  |  |  |  |  |  |
|--|--|--|--|--|--|--|--|--|--|
|  |  |  |  |  |  |  |  |  |  |
|--|--|--|--|--|--|--|--|--|--|

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: [CRP, location mowed](#)**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_



1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

**Overall Interim Reclamation****Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs                          | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Pass                  |  |                          |         |
| Compaction       | Pass            | Compaction              | Pass                  | Material Handling And Spill Prevention | Pass                     |         |

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NO

Pit ID: \_\_\_\_\_

Lat: \_\_\_\_\_

Long: \_\_\_\_\_

Reference Point: \_\_\_\_\_

Other: \_\_\_\_\_

Length: \_\_\_\_\_

Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_

Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: c**Fencing:**Fencing Type: None

Fencing Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_

Netting Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_

Oil Accumulation: NO2+ feet Freeboard: YESComment: on west side of road

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Type: Produced WaterLined: NO

Pit ID: \_\_\_\_\_

Lat: \_\_\_\_\_

Long: \_\_\_\_\_

Reference Point: \_\_\_\_\_

Other: \_\_\_\_\_

Length: \_\_\_\_\_

Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_

Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: c**Fencing:**Fencing Type: None

Fencing Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_

Netting Condition: \_\_\_\_\_

|                             |  |                             |                               |       |                |
|-----------------------------|--|-----------------------------|-------------------------------|-------|----------------|
| Comment:                    |  |                             |                               |       | Date:          |
| Corrective Action           |  |                             |                               |       |                |
| Anchor Trench Present:      |  | Oil Accumulation: <u>NO</u> | 2+ feet Freeboard: <u>YES</u> |       |                |
| Comment:                    | <u>Pit on east side of access road to the southeast of VHT</u> |                             |                               |       | Date:          |
| Corrective Action           |  |                             |                               |       |                |
| Type: <u>Produced Water</u> | Lined: <u>NO</u>   | Pit ID:                     | Lat:                          | Long: |                |
| Reference Point:            | Other:   | Length:                     | Width:                        |       |                |
| <u>Lining:</u>              |  |                             |                               |       |                |
| Liner Type:                 |  | Liner Condition:            |                               |       |                |
| Comment:                    |  |                             |                               |       | Date: <u>c</u> |
| Corrective Action           |  |                             |                               |       |                |
| <u>Fencing:</u>             |  |                             |                               |       |                |
| Fencing Type: <u>None</u>   |  | Fencing Condition:          |                               |       |                |
| Comment:                    |  |                             |                               |       | Date:          |
| Corrective Action           |  |                             |                               |       |                |
| <u>Netting:</u>             |  |                             |                               |       |                |
| Netting Type:               |  | Netting Condition:          |                               |       |                |
| Comment:                    |  |                             |                               |       | Date:          |
| Corrective Action           |  |                             |                               |       |                |
| Anchor Trench Present:      |  | Oil Accumulation: <u>NO</u> | 2+ feet Freeboard: <u>YES</u> |       |                |
| Comment:                    | <u>Pit on east side of access road E of VHT.</u>               |                             |                               |       | Date:          |
| Corrective Action           |  |                             |                               |       |                |
| Type: <u>Produced Water</u> | Lined: <u>NO</u>   | Pit ID:                     | Lat:                          | Long: |                |
| Reference Point:            | Other:   | Length:                     | Width:                        |       |                |
| <u>Lining:</u>              |  |                             |                               |       |                |
| Liner Type:                 |  | Liner Condition:            |                               |       |                |
| Comment:                    |  |                             |                               |       | Date: <u>c</u> |
| Corrective Action           |  |                             |                               |       |                |
| <u>Fencing:</u>             |  |                             |                               |       |                |
| Fencing Type: <u>None</u>   |  | Fencing Condition:          |                               |       |                |
| Comment:                    |  |                             |                               |       | Date:          |
| Corrective Action           |  |                             |                               |       |                |
| <u>Netting:</u>             |  |                             |                               |       |                |
| Netting Type:               |  | Netting Condition:          |                               |       |                |
| Comment:                    |  |                             |                               |       | Date:          |
| Corrective Action           |  |                             |                               |       |                |
| Anchor Trench Present:      |  | Oil Accumulation: <u>NO</u> | 2+ feet Freeboard: <u>YES</u> |       |                |

|                   |               |       |
|-------------------|---------------|-------|
| Comment:          | Near wellhead | Date: |
| Corrective Action |               |       |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description      | URL   |
|--------------|------------------|---|
| 688302188    | Fritzler Cronk 1 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4516528">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4516528</a> |