



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern portion of the project area from the northeastern corner facing westward. Revegetation is progressing with grasses and shrubs such as rubber rabbitbrush (*Chrysothamnus nauseosus*), antelope bitterbrush (*Purshia tridentata*), blue grama (*Bouteloua gracilis*).



Photo 3. View of the eastern portion of the project area from the northeastern corner facing southward.



Photo 4. View of plastic debris along the edge of the eastern fenceline.



Photo 5. View of more plastic debris along the eastern project area.



Photo 6. View of erosional channel approximately 3 feet wide and 1.5 feet deep in the eastern portion of the project area that needs stabilization.



Photo 7. View of more erosional channels in the eastern portion of the project area.



Photo 8. View of Russian knapweed (*Rhaponticum repens*) on the well pad.



Photo 9. View of musk thistles (*Carduus nutans*) along the access road.