



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern portion of the project area from the northeastern corner facing southward. Revegetation is sparse with widely spaced rubber rabbitbrush (*Chrysothamnus nauseosus*) and grasses in a dormant or deceased state.



Photo 3. View of the western portion of the project area from the northwestern corner facing southward.



Photo 4. View unused equipment within the eastern project area.



Photo 5. View of housing equipment that does not appear to be in use.



Photo 6. View of typical grass within the interim reclamation that is in poor condition.



Photo 7. View of silt trap in the northeastern portion of the project area.



Photo 8. View of silt trap in the northwestern project area.