

Final Reclamation and Stormwater Inspection

June 28, 2018

Operator: PIONEER NATURAL RESOURCES USA INC – 10084

Location ID: 383608

Inspection Document #: 674902268

Huerfano County, CO

SENE Section 25 T29S R67W

Russell Beam
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: PIONEER NATURAL RESOURCES USA INC /29S67W25

Location ID: 383608



Photo 1. Photo taken from the access road looking towards the location, facing East. Appears the Operator has performed final reclamation activities on the well location and access road.



Photo 2. Photo taken from the well location, facing North. See comments from Photo 1.

Inspection Photos

Location Name: PIONEER NATURAL RESOURCES USA INC /29S67W25

Location ID: 383608



Photo 3. Photo taken from the well location, facing East. See comments from Photo 1.



Photo 4. Photo taken from the well location, facing South. See comments from Photo 1.

Inspection Photos

Location Name: PIONEER NATURAL RESOURCES USA INC /29S67W25

Location ID: 383608



Photo 5. Photo taken from the well location, facing West. See comments from Photo 1.



Photo 6. Photo taken from the West end of the location. Note the gravel stockpile that was not removed.

Inspection Photos

Location Name: PIONEER NATURAL RESOURCES USA INC /29S67W25

Location ID: 383608



Photo 7. Photo taken from the access road. Note the culvert that is still on location.



Photo 8. Photo taken from the access road, facing South. See comments from Photo 7.

Inspection Photos

Location Name: PIONEER NATURAL RESOURCES USA INC /29S67W25

Location ID: 383608



Photo 9. Photo taken from the Reference Area, facing North.



Photo 10. Photo taken from the Reference Area, facing East.

Inspection Photos

Location Name: PIONEER NATURAL RESOURCES USA INC /29S67W25

Location ID: 383608



Photo 11. Photo taken from the Reference Area, facing South.



Photo 12. Photo taken from the Reference Area, facing West.