

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/06/2018

Submitted Date:

07/09/2018

Document Number:

688800203**FIELD INSPECTION FORM**

Loc ID 333983 Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Operator Information:OGCC Operator Number: 5Name of Operator: COLORADO OIL & GAS CONSERVATIONAddress: 1120 LINCOLN ST SUITE 801City: DENVER State: CO Zip: 80203**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298285	WELL	SI	06/15/2015	OBW	007-06264	FOSSET GULCH MW 34-5-14 1	EI
298286	WELL	SI	06/15/2015	OBW	007-06265	FOSSET GULCH MW 34-5-14 2	EI

General Comment:

On July 6, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the COGCC Fossett Gulch MW 34-5-14 #1 and #2. For the most recent field inspection report for this facility, please refer to document #674901756.

Location

Lease Road:			
Type	Main		
comment:	Location is road side along Forest Service Road 613.		
Corrective ActionL		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Location signs mounted to protective barricades surrounding well heads. Township in well name is incorrect. Legal description on sign is accurate.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	Sign mounted to protective barricade surrounding ancillary equipment.		
Corrective Action:		Date:	_____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Steel pipe protective barricade fencing surrounding well heads and ancillary equipment.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	In-Situ data logger.		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 298285 Type: WELL API Number: 007-06264 Status: SI Insp. Status: EI

Facility ID: 298286 Type: WELL API Number: 007-06265 Status: SI Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>On July 6, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the COGCC Fossett Gulch MW 34-5-14 #1 and #2. For the most recent field inspection report for this facility, please refer to document #674901756.</p> <p>During this field inspection, it was observed that the emergency contact information sign had partially fallen off of the barricade. The sign was reattached to the steel pipe barricade fencing.</p> <p>Eight desiccant packets and one Desi-tube were replaced during this field inspection. The desiccants were last replaced on 6/12/17.</p> <p>No corrosion was observed on the battery terminals.</p>	hughesj	07/09/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800204	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4517250