

**Inspection Photos**  
**Location Name: Tierra Piedra SWD Facility**  
**API: 05-007-06307**



County code on sign for side track #3 is incorrect.



Tierra Piedra 33-3-15 #1R (API # 007-06269) well head.

**Inspection Photos**  
**Location Name: Tierra Piedra SWD Facility**  
**API: 05-007-06307**



**Tierra Piedra 33-5 #15-1 SWD well head within fiberglass shack.**



**Chemical injection systems on secondary containment.**



**Inspection Photos**  
**Location Name: Tierra Piedra SWD Facility**  
**API: 05-007-06307**



**West side of injection pump house with stained soil present.**



**Southwest corner of injection pump house with wet/stained soil and corroded metal .**

**Inspection Photos**  
**Location Name: Tierra Piedra SWD Facility**  
**API: 05-007-06307**



**Staining on western produced water AST.**



**Penetration through liner and secondary containment ring where release reportedly occurred.**