

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/06/2018

Submitted Date:

07/09/2018

Document Number:

688800207**FIELD INSPECTION FORM**Loc ID 334009 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 5Name of Operator: COLORADO OIL & GAS CONSERVATIONAddress: 1120 LINCOLN ST SUITE 801City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299319	WELL	SI	06/15/2015	OBW	007-06270	HWY 151 34-4-30 MW 2	EI
299320	WELL	SI	06/15/2015	OBW	007-06271	HWY 151 34-4-30 MW 1	EI

General Comment:

On July 6, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the COGCC Highway 151 34-4-30 MW #1 and #2. For the most recent field inspection report of this facility, please refer to document #674901753.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing signs located near location entrance.		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Sign mounted to stock panel enclosure.		
Corrective Action:		Date:	

Good Housekeeping:			
Type	WEEDS		
Comment:	Monitor weeds during growing season.		
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Stock panel enclosure.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	In-Situ data logger.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	299319	Type:	WELL	API Number:	007-06270	Status:	SI	Insp. Status:	EI
Facility ID:	299320	Type:	WELL	API Number:	007-06271	Status:	SI	Insp. Status:	EI

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On July 6, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the COGCC Highway 151 34-4-30 MW #1 and #2. For the most recent field inspection report of this facility, please refer to document #674901753. The purpose of this site visit was to replace the desiccants within the equipment enclosures. Eight desiccant packets and one Desi-Tube were replaced. The desiccants were last replaced on 6/12/17. No corrosion was observed on the battery terminals.	hughesj	07/09/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800208	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4517861