

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/09/2018

Submitted Date:

07/10/2018

Document Number:

680303508

FIELD INSPECTION FORM

Loc ID 312161 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10380
Name of Operator: BENCHMARK ENERGY LLC
Address: PO BOX 8747
City: PRATT State: KS Zip: 67124

Findings:

- 5 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Sutphin, Dirk		dirk.sutphin@state.co.us	

General Comment:

Benchmark Project - ODO Program - P&A Complete Doc#680303451 & 680303508. Wellhead cut-off, welded cap w/info., backfilled. Flowlines and anchors remain in place. Contact COGCC Reclamation Group for surface reclamation.

Location

Lease Road:			
Type	Access		
comment:	Maintain lease road until final reclamation is approved.		
Corrective Action:		Date:	

Overall Good:

Emergency Contact Number:	
Comment:	<input style="width: 100%;" type="text"/>
Corrective Action:	<input style="width: 100%;" type="text"/>
Date:	_____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Flow Line	#		
Comment:	Flowlines remain in place		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:	Anchors remain in place		
Corrective Action:		Date:	
Type: Other	# 0		
Comment:	No production equipment @ wellhead site.		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	