

GV 17-32
Api# 05-045-06629
Inspection # 689701592



Location photo

GV 17-32
Api# 05-045-06629
Inspection # 689701592



BMPs have maintained.

GV 17-32
Api# 05-045-06629
Inspection # 689701592



BMPs have been maintained.

GV 17-32
Api# 05-045-06629
Inspection # 689701592



Fence panels off the side of road at Y into tank facility.

GV 17-32
Api# 05-045-06629
Inspection # 689701592



Barb wire under tree at facility Y entrance.

Fence wire on road into facility.