

PUCKETT 12-31D
Api# 05-045-07757
Inspection # 689701600



Well pad photo

PUCKETT 12-31D
Api# 05-045-07757
Inspection # 689701600



PUCKETT 12-31D
Api# 05-045-07757
Inspection # 689701600



Fallen rock from unstable cut slope.

PUCKETT 12-31D
Api# 05-045-07757
Inspection # 689701600



Fallen rock from unstable cut slope.

PUCKETT 12-31D
Api# 05-045-07757
Inspection # 689701600



Fallen rock from unstable cut slope.

PUCKETT 12-31D
Api# 05-045-07757
Inspection # 689701600



Damaged jersey barrier.



Damaged jersey barrier.

PUCKETT 12-31D
Api# 05-045-07757
Inspection # 689701600



Fallen rock from unstable cut slope.

PUCKETT 12-31D
Api# 05-045-07757
Inspection # 689701600



Electric cable cut, buried and exposed across location to wells.



Electric cable cut, buried and exposed across location to wells.

PUCKETT 12-31D
Api# 05-045-07757
Inspection # 689701600



Washing of road up to well pad from tank facility.