

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/06/2018

Submitted Date:

07/11/2018

Document Number:

691300353**FIELD INSPECTION FORM**
 Loc ID 455340 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10459Name of Operator: EXTRACTION OIL & GAS INCAddress: 370 17TH STREET SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Adamczyk, Megan		megan.adamczyk@state.co.us	
,		COGCCInspections@extracti onog.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
455610	WELL	DG	07/02/2018		123-47174	Rinn Valley East N17-20-9N	DG

General Comment:

Inspected Facilities

Facility ID: 455610 Type: WELL API Number: 123-47174 Status: DG Insp. Status: DG

Complaint

Comment: [Inspection in response to complaint.](#)

[Field Inspector Assigned: Adam Kraich](#)

[Complaint Received:](#)

[Date: 7/6/2018](#)

[Complaint Contacted: 15:45](#)

[Date: 7/6/2018](#)

[Location #: 455340](#)

[Inspection Document #: 691300353](#)

[Nature of complaint: Noise](#)

[Field Inspector Actions:](#)

[On 7/6/2018; I received a complaint in regards to noise and odors suspected to be originating from the Rinn Valley Pad operated by extraction.](#)

[On 7/6/2018; I visited the location to find the surface drilling unit \(Cartel #11\) on location. The rig was in process of setting surface casing at the time of inspection.](#)

[On 7/6/2018, I performed a sound audit at 70.13165, -105.03725 \(Approximately 350' SE of the rig\). The temperature was 79° with a wind speed of 2.7 mph out of the southeast. Audit shows an average of 60.4 DB. Please see attached sound audit for data.](#)

[No odors were observed either on, or off location at time of inspection.](#)

[No violation of COGCC rules were observed at the time of the inspection.](#)

[All information reviewed and site inspection information were submitted to the complaint specialist for further review.](#)

Corrective Action:

Date:

Well Drilling

Rig: Rig Name: Cartel #11 Pusher/Rig Manager: _____
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: _____ Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: _____

Comment: [Surface casing rig](#)

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
Inspection in response to complaint	kraicha	07/11/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691300354	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4519606
691300355	Sound Audit	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4519607