

DAVID A COOK  
FRAM OPERATING LLC  
6 SOUTH TEJON STREET #400  
Colorado Springs, CO 80903

Dear Mr. Cook,

FRAM OPERATING LLC is receiving this letter because, based on COGCC records, the COGCC has reason to believe that in addition to the Well on the Warning Letter the Wells provided below present one or more compliance issues. The Wells provided below must be brought into compliance or be compliant by the date provided on the Warning Letter. Please do not hesitate to contact me with any questions regarding this compliance issue, or if these Wells are incorrectly reported as non-compliant.

1. EBERLY 23-4-API#077-08886
2. DOTY 1-1-API#077-08872
3. MANSUR 33-4-C-API#077-09474
4. JENSEN 1-3-API#077-08922
5. Eberly #23-4-M-API#077-09314
6. HAMILTON 32-4-API#029-06101
7. HAMILTON 33-3-API#029-06102

Thank you,

**Ryan Daigle**

Engineering Technician



P 303.894.2100 x5168 | F 303.894.2105

1120 Lincoln Street, Suite 801, Denver, CO 80203

[ryan.daigle@state.co.us](mailto:ryan.daigle@state.co.us) | [www.colorado.gov/cogcc](http://www.colorado.gov/cogcc)