

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/11/2018

Submitted Date:

07/12/2018

Document Number:

687902736

**FIELD INSPECTION FORM**

Loc ID 334201 Inspector Name: DURAN, JOHN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10084  
Name of Operator: PIONEER NATURAL RESOURCES USA INC  
Address: 5205 N O'CONNOR BLVD STE 200  
City: IRVING State: TX Zip: 75039

**Findings:**

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277846	WELL	PR	08/15/2005	GW	071-08387	SAMBUCA 31-13	PR
290926	WELL	PR	09/14/2007	GW	071-09323	SAMBUCA 31-13 TR	PR

**General Comment:**

*(This area is intentionally left blank for general comments.)*

**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Fencing/:**

	Type PUMP JACK		
Comment:			
Corrective Action:			Date:

**Equipment:**

					corrective date
Type: Progressive Cavity	# 1				
Comment:					
Corrective Action:					Date:
Type: Gas Meter Run	# 2				
Comment:					
Corrective Action:					Date:
Type: Pump Jack	# 1				
Comment:					
Corrective Action:					Date:
Type: Deadman # & Marked	# 8				
Comment:					
Corrective Action:					Date:
Type: Vertical Separator	# 2				
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 277846 Type: WELL API Number: 071-08387 Status: PR Insp. Status: PR

**Producing Well**

Comment: [PR - Calibration Report \(05/30/17\)\(Photo\)](#).

Corrective Action: [Need to update Calibration Report.](#)

Date: 08/12/2018

Facility ID: 290926 Type: WELL API Number: 071-09323 Status: PR Insp. Status: PR

**Producing Well**

Comment: [PR - Calibration Report \(05/30/17\)\(Photo\)](#).

Corrective Action: [Need to update Calibration Report.](#)

Date: 08/12/2018

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID:      Lat:      Long:

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_      Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: c

**Fencing:**

Fencing Type: \_\_\_\_\_      Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_      Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_      Oil Accumulation: NO      2+ feet Freeboard: YES

Comment: 30' x 70'

Corrective Action

Date: \_\_\_\_\_

Type: Produced Water      Lined: NO      Pit ID:      Lat:      Long:

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_      Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: c

**Fencing:**

Fencing Type: \_\_\_\_\_      Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_      Netting Condition: \_\_\_\_\_

<b>Comment:</b>				<b>Date:</b>
<b>Corrective Action</b>				
<b>Anchor Trench Present:</b>		<b>Oil Accumulation:</b> <u>NO</u>	<b>2+ feet Freeboard:</b> <u>YES</u>	
<b>Comment:</b>	<u>30' x 70'</u>			<b>Date:</b>
<b>Corrective Action</b>				
<b>Permit:</b>	<b>Facility ID</b>	<b>Permit Num</b>	<b>Expiration Date</b>	
	301036	200253306		
	301036	1941924		
	281102	1393353		
<b>Monitoring:</b>	<b>Monitoring Type</b>		<b>Comment`</b>	
	Chain		Yellow	
	Chain		Yellow	

**COGCC Comments**

Comment	User	Date
<a href="#">SEE : Related Facility : Calibration Report</a>	duranj	07/11/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687902737	Lease sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4520910">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4520910</a>
687902738	Calibration Report	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4520911">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4520911</a>
687902739	Well pad	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4520912">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4520912</a>
687902740	Lease sign	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4520913">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4520913</a>
687902741	Well pad	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4520914">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4520914</a>
687902742	Calibration Report	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4520915">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4520915</a>