

Photo log for Response to June 12, 2018 Inspection

COGCC conducted an inspection of the Lilli Unit 16-6 location (Location ID 326799) on June 12, 2018 (Document 684905510). During that inspection, COGCC made the following observation:

Storm Water: Stormwater erosion S of wellhead. Install or repair required BMPs per Rule 1002.f.

Response: Noble repaired the erosion.

COGCC – 6/12/18



COGCC Photo 3: Stormwater erosion at S of wellhead

Noble Energy – 6/28/18



Photo NBL1. Noble repaired the erosion.