

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/12/2018

Submitted Date:

07/13/2018

Document Number:

689301511

**FIELD INSPECTION FORM**

Loc ID 334852 Inspector Name: Holtz, Darin On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Findings:**

7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Elsener,		COGCC.inspections@caerus oilandgas.com	<a href="#">all Piceance inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211179	WELL	TA	10/01/2017	GW	045-06938	KRK 7-11	TA
264658	WELL	SI	10/01/2017	GW	045-08934	KRK 7-5D (K7)	TA
264659	WELL	PR	01/12/2003	GW	045-08935	KRK 7-11C (K7)	PR
264660	WELL	SI	01/01/2018	GW	045-08933	KRK 7-6D (D7)	PR

**General Comment:**

[On site to witness MIT for 045-06938](#)

[Routine Field Inspection](#)

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Emergency Contact Number:			
Comment:	1-800-791-7691		
Corrective Action:			Date:

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:			
Corrective Action:			Date:
Type	TRASH		
Comment:			
Corrective Action:			Date:
Type	DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 2		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Vertical Heated Separator	# 4		

Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		

Comment:	Centralized Battery	
Corrective Action:		Date:

**Paint**

Condition	Adequate	
Other (Content)	Methanol Tank	
Other (Capacity)	1000 & 500 gallon	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	
Corrective Action:	Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 211179 Type: WELL API Number: 045-06938 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: 10 day MIT notification recieved. Document #401689536. D&B water services on site to perform test.  
 Starting psi -400  
 5 min- psi- 398  
 10 min- psi- 398  
 Final PSI-394  
 PSI lose 6

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 264658 Type: WELL API Number: 045-08934 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 264659 Type: WELL API Number: 045-08935 Status: PR Insp. Status: PR

**Producing Well**

Comment: Well Producing on plunger lift

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 264660 Type: WELL API Number: 045-08933 Status: SI Insp. Status: PR

**Producing Well**

Comment: Well Producing on plunger lift

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:  Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding						
		Gravel				
Berms						
		Compaction				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689301515	Inspection Photo 689301515	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4522198">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4522198</a>