

Inspection Photos  
Location Name: Pinnacle Unit 12-30  
API: 05-103-05906



**Photo 1. Overview of location taken at entrance facing south.**

API: 05-103-05906



**Photo 2. Stained soil on tank berm.**

[illegible]

**Photo 3. Form 21 for failed test.**