

Inspection Photos
Location Name: Carpenter 2-32
API: 05-081-05363



Photo 1. Overview of location taken at entrance facing southeast.