



**Location**

<b>Lease Road:</b>			
Type	Main		
comment:	Main road to Cache 8-34 (API# 05-123-24412), Cache 8-13 (API# 05-123-24410), Cache 8-23 (API# 05-123-24411), Cache 8-24 (API# 05-123-25427), Cache 8-33 (API# 05-123-25665), Cornish 8-53 (API# 05-123-32190) is adequate.		
Corrective ActionL		Date:	
Type	Access		
comment:	Access road to Cache 8-13 (API# 05-123-24410) is adequate. 2-Track Ag road.		
Corrective ActionL		Date:	

Overall Good:

<b>Emergency Contact Number:</b>			
Comment:	No emergency contact number at wellhead.		
Corrective Action:	Install sign to comply with rule 210.b.		Date: 08/13/2018

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type			
Comment:	Refer to FIR# 691200244 for additional fencing list for this facility.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cache 8-13 (API# 05-123-24410) has iron panel fencing.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type:	#		
Comment:	Refer to FIR# 691200244 for complete equipment list for this facility.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.499062,-104.461664
Comment:	This centralized battery serves 6 locations (306312, 306310, 306311, 309823, 309973, 419186). Refer to FIR# 691200244 for Tanks & Berms info regarding this facility.				
Corrective Action:				Date:	

<b>Paint</b>				
Condition				
Other (Content)				
Other (Capacity)				
Other (Type)				
<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:
<b>Venting:</b>				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 287758 Type: WELL API Number: 123-24410 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Well appears to be SI at separator.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Comment: Bradenhead appears to be plumbed to surface.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
New Cache FH # 8-32D (API# 05-123-36968), New Cache FH # 8-12D (API# 05-123-36969), New Cache FH # 8-33D (API# 05-123-36970) have never been drilled.	evinsb	07/13/2018

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691200248	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4523572">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4523572</a>