

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/04/2018

Submitted Date:

07/08/2018

Document Number:

689701580**FIELD INSPECTION FORM**Loc ID 322542 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments2 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210766	WELL	PR	12/28/1986	GW	045-06524	HOAGLUND W-33-2	PR

General Comment:[Follow up to inspection 7/6/2018 Doc \[#689701324\]](#)

Corrective action are not completed. Storm water issues no actions taken. Erosion rill not repaired, sediment build up still in ditch at paved entrance. Trash pile has been picked up but some debris left.

Location**Lease Road:**

Type	Access		
comment:	Road appears to have been dragged. Lagre stones in roadway.		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	970-285-9377	Date:	
Corrective Action:			

Good Housekeeping:

Type	TRASH		
Comment:	C.A. from previous inspection: Trash dumped on side of access road. Trash at county road and access gate. Majority of trash has been removed. Debris from trash still left. There is some trash (beer cans) at entrance.		
Corrective Action:	Comply with Rule 603.f .	Date:	05/15/2018
Type	WEEDS		
Comment:	Evidence of weeds treated and mowed or dragged. Continue weed control.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 210766	Type: WELL	API Number: 045-06524	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Washing and erosion from ruts down road. Sediment build up in ditch at entrance gate of access road from county road. Sediment moving on to county road and paved entrance.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 06/08/2018

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401695888	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4516501
689701581	Inspection 689701580 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4516499