



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern portion of the project area from the southwestern corner facing eastward. Very little vegetative cover observed here.



Photo 3. View of the western portion of the project area from the southwestern corner facing northward.



Photo 4. View of erosional channels in the western project area.



Photo 5. View of diversion in the northwestern project area needing stormwater controls to de-energize stormwater flows exiting the project area.