

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/16/2018

Submitted Date:

07/17/2018

Document Number:

687902797**FIELD INSPECTION FORM**
 Loc ID 308294 Inspector Name: DURAN, JOHN On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10084Name of Operator: PIONEER NATURAL RESOURCES USA INCAddress: 5205 N O'CONNOR BLVD STE 200City: IRVING State: TX Zip: 75039**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Pioneer	972-444-9001	COGCC.Inspections@pxd.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265603	WELL	PR	02/27/2005	GW	071-07780	SHINARUMP 11-11 TR	PR
415060	WELL	AL	01/25/2012	LO	071-09784	Shinarump 11-11 Kv	AL

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign has Qtr - Qtr of NENW (Photo). The Footages are : 947 FNL , 414 FWL --- This puts it in the NWNW.		
Corrective Action:	Need to change Qtr -Qtr on lease sign from NENW to NWNW.	Date:	08/16/2018

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Progressive Cavity	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 5		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 265603 Type: WELL API Number: 071-07780 Status: PR Insp. Status: PR**Producing Well**Comment: [PR - Calibration Report : \(06/08/17\)\(Photo\).](#)Corrective Action: [Need to update Calibration Report.](#)Date: 08/16/2018Facility ID: 415060 Type: WELL API Number: 071-09784 Status: AL Insp. Status: AL

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Produced WaterLined: NOPit ID: Lat: Long: Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment: Corrective Action: Date: c**Fencing:**Fencing Type: Fencing Condition: Comment: Corrective Action: Date: **Netting:**Netting Type: Netting Condition: Comment: Corrective Action: Date: Anchor Trench Present: Oil Accumulation: NO2+ feet Freeboard: YESComment: 30' x 70'Corrective Action: Date:

Permit:	Facility ID	Permit Num	Expiration Date
	270495	1126106	
	270495	1126106	

Monitoring:	Monitoring Type	Comment
	Chain	Orange

COGCC Comments

Comment	User	Date
SEE : Related Facility : Calibration Report. SEE : Signs/Marker : Incorrect Qtr -Qtr.	duranj	07/17/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687902801	Lease sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4525028

687902802	Well pad	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4525029
687902803	Calibration Report	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4525030