



Photo 1. View of the project area from the well pad entrance facing center. Area is mowed and herbicide applied around facilities.



Photo 2. View of the southeastern portion of the project area from the entrance to the well pad facing southward.



Photo 3. View of the northern portion of the project area from the well pad entrance facing westward.