

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/17/2018

Submitted Date:

07/17/2018

Document Number:

691200266

FIELD INSPECTION FORM

Loc ID 319086 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 8960
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
Address: 410 17TH STREET SUITE #1400
City: DENVER State: CO Zip: 80202

Findings:

- 8 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
,		EHSRC@bonanzacrk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242860	WELL	PR	01/01/2014	OW	123-10651	WILDFONG 11-23	PR

General Comment:

(This area is currently blank for general comments.)

Location

Lease Road:			
Type	Access		
comment:	Access road to Wildfong 11-23 (API# 05-123-10651) well is adequate. 2-Track Ag road.		
Corrective Action		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign not posted at wellhead.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	09/17/2018

Emergency Contact Number:			
Comment:	No emergency contact information at wellhead.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	08/30/2018

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	Natural gas engine powers pumping unit.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 242860 Type: WELL API Number: 123-10651 Status: PR Insp. Status: PR

Producing Well

Comment: Well is producing. Pum jack in operation.

Corrective Action:

Date:

BradenHead

Comment: Bradenhead appears to be plumbed to surface.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<u>Inspected well only at this time. Didn't inspect battery.</u>	evinsb	07/17/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691200267	Site photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4525994