


DOE PM 2-31
Api# 05-045-07036
Inspection # 689701621



Location photo

DOE PM 2-31
Api# 05-045-07036
Inspection # 689701621



Tubing off the edge of location. 39.48637 -108.04253

DOE PM 2-31
Api# 05-045-07036
Inspection # 689701621



Tubing off the edge of location. 39.48637 -108.04253

DOE PM 2-31
Api# 05-045-07036
Inspection # 689701621



Erosion of hillside from ditch run off at top switch back. (39.48567 108.04314)

DOE PM 2-31
Api# 05-045-07036
Inspection # 689701621



**Sediment build up over straw bales used for check dams @ Switch back
(39.48597 108.04075)**

DOE PM 2-31
Api# 05-045-07036
Inspection # 689701621



**Erosion of hillside from ditch run off and rilling of roadside @ (39.48523
108.04113)**

DOE PM 2-31
Api# 05-045-07036
Inspection # 689701621



**Erosion of hillside from ditch run off and rilling of roadside @ (39.48523
108.04113)**

DOE PM 2-31
Api# 05-045-07036
Inspection # 689701621



Erosion of hillside from ditch run off @ (39.48382 108.04018)